



**WARNING:** This distributor is not compatible with stock points distributor coil, must use high output coil. Must bypass ballast resistor if applicable.